



# Mellanox Switch-IB Firmware Release Notes

---

Rev 11.1500.0106



NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT (PRODUCT(S)) AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES AS-IS WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS. THE CUSTOMER'S MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies  
350 Oakmead Parkway Suite 100  
Sunnyvale, CA 94085  
U.S.A.  
[www.mellanox.com](http://www.mellanox.com)  
Tel: (408) 970-3400  
Fax: (408) 970-3403

© Copyright 2017. Mellanox Technologies Ltd All Rights Reserved

Mellanox®, Mellanox logo, Accelio®, BridgeX®, CloudX logo, CompustorX®, ConnectIB®, ConnectX®, CoolBox®, CORE-Direct®, EZchip®, EZchip logo, EZappliance®, EZdesign®, EZdriver®, EZsystem®, GPUDirect®, InfiniHost®, InfiniBridge®, InfiniScale®, Kotura®, Kotura logo, Mellanox CloudRack®, Mellanox CloudXMellanox®, Mellanox Federal Systems®, Mellanox HostDirect®, Mellanox Multi-Host®, Mellanox Open Ethernet®, Mellanox OpenCloud®, Mellanox OpenCloud Logo®, Mellanox PeerDirect®, Mellanox ScalableHPC®, Mellanox StorageX®, Mellanox TuneX®, Mellanox Connect Accelerate Outperform logo, Mellanox Virtual Modular Switch®, MetroDX®, MetroX®, MLNX-OS®, NP-1c®, NP-2®, NP-3®, NPS®, Open Ethernet logo, PhyX®, PlatformX®, PSIPHY®, SiPhy®, StoreX®, SwitchX®, Tiler®, Tiler logo, TestX®, TuneX®, The Generation of Open Ethernet logo, UFM®, Unbreakable Link®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies Ltd.

All other trademarks are property of their respective owners

For the most updated list of Mellanox trademarks visit <http://www.mellanox.com/page/trademarks>



## Table of Contents

|   |           |
|---|-----------|
| <b>Chapter 1 Overview</b>                                     | <b>4</b>  |
| 1.1 Supported Systems   | 4         |
| 1.2 Firmware Interoperability                                 | 4         |
| 1.3 Supported EDR Cables and Modules                          | 4         |
| 1.4 Firmware Upgrade  | 5         |
| 1.5 PRM Revision Compatibility                                | 5         |
| <b>Chapter 2 Changes and New Features in Rev 11.1500.0106</b> | <b>6</b>  |
| <b>Chapter 3 Known Issues</b>                                 | <b>7</b>  |
| <b>Chapter 4 Bug Fixes History</b>                            | <b>9</b>  |
| <b>Chapter 5 Firmware Changes and New Feature History</b>     | <b>11</b> |





## List of Tables

|          |  |    |
|----------|--|----|
| Table 1: | Release Update History                             | 3  |
| Table 2: | Supported Systems                                  | 4  |
| Table 3: | Firmware Interoperability                          | 4  |
| Table 4: | Qualified EDR Cables                               | 4  |
| Table 5: | Firmware Rev 11.1500.0106 Changes and New Features | 6  |
| Table 6: | Known Issues                                       | 7  |
| Table 7: | Fixed Bugs List                                    | 9  |
| Table 8: | History of Major Changes and New Features          | 11 |



## Release Update History

*Table 1 - Release Update History*

| Release          | Date               | Description  |
|------------------|--------------------|--|
| Rev 11.1500.0106 | August 31, 2017    | First release  |
|                  | September 19, 2017 | <ul style="list-style-type: none"><li>• Added “Modules” new feature to Chapter 2, “Changes and New Features in Rev 11.1500.0106,” on page 6</li><li>• Added bug fix to Table 7, “Fixed Bugs List,” on page 9</li></ul> |

# 1 Overview

These are the release notes for the Switch-IB™ firmware, Rev 11.1500.0106. This firmware complements the Switch-IB™ silicon architecture with a set of advanced features, allowing easy and remote management of the switch.



Firmware Rev 11.1500.0106 is compatible with MFT tools v4.7.0-42. Using older versions of MFT tools causes failure during image creation.

## 1.1 Supported Systems

This firmware supports the devices and protocols listed in [Table 2](#). For the most updated list of switches supported, visit the Firmware Download pages on Mellanox.com.

**Table 2 - Supported Systems**

| Device Part Number | Description   |
|--------------------|---|
| MSB7790            | Switch-IB™ based EDR InfiniBand switch; 36 QSFP28 ports; externally managed |

## 1.2 Firmware Interoperability

To raise links with platforms based on the following ICs, these minimum requirements must be met:

**Table 3 - Firmware Interoperability**

| HCA/Switch        | Firmware Version |
|-------------------|------------------|
| Switch-IB™ 2      | 15.1200.0102     |
| SwitchX®-2        | 9.2.8000         |
| ConnectX®-5 (Ex)  | 16.18.1000 Beta  |
| ConnectX®-4       | 12.18.2000       |
| ConnectX®-4 Lx    | 14.18.1000       |
| ConnectX®-3 (Pro) | 2.40.7000        |
| ConnectX®-2       | 2.9.1200         |
| Connect-IB®       | 10.16.1020       |

## 1.3 Supported EDR Cables and Modules

[Table 4](#) presents the qualified EDR cables for externally managed EDR switch systems.

**Table 4 - Qualified EDR Cables**

| Mellanox P/N | Description  | Cable Length |
|--------------|--|--------------|
| MMS1C00-C500 | Mellanox® transceiver, 100GbE, QSFP28, MPO, 1550nm PSM4, up to 2km | -            |
| MMS1C10-CM   | Mellanox® active optical module, 100Gb/s, QSFP, MPO, 1310nm, PSM4  | -            |



**Table 4 - Qualified EDR Cables**

| Mellanox P/N              | Description  | Cable Length |
|---------------------------|--|--------------|
| MMA1L10-CR                | Mellanox® optical transceiver, 100GbE, 100Gb/s, QSFP28, LC-LC, 1310nm, LR4, up to 10km | -            |
| MCP1600-E00A <sup>a</sup> | Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH                            | 0.5m         |
| MCP1600-E001 <sup>a</sup> | Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH                            | 1m           |
| MCP1600-E01A <sup>a</sup> | Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH                            | 1.5m         |
| MCP1600-E002 <sup>a</sup> | Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH                            | 2m           |
| MCP1600-E02A              | Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH                            | 2.5m         |
| MCP1600-E003              | Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH                            | 3m           |
| MCP1600-E004              | Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH                            | 4m           |
| MFA1A00-E005 <sup>a</sup> | Mellanox® active fiber cable, up to 100Gb/s, QSFP28                                    | 5m           |
| MFA1A00-E010 <sup>a</sup> | Mellanox® active fiber cable, up to 100Gb/s, QSFP28                                    | 10m          |
| MFA1A00-E015 <sup>a</sup> | Mellanox® active fiber cable, up to 100Gb/s, QSFP28                                    | 15m          |
| MFA1A00-E050              | Mellanox® active fiber cable, up to 100Gb/s, QSFP28                                    | 50m          |
| MFA1A00-E100              | Mellanox® active fiber cable, up to 100Gb/s, QSFP28                                    | 100m         |

a. Forward Error Correction (FEC) is deactivated on this cable.

**Modules** Please refer to the LinkX™ Cables and Transceivers webpage for the full list of supported cables and transceivers <http://www.mellanox.com/products/interconnect/cables-configurator.php>

## 1.4 Firmware Upgrade

Firmware upgrade may be performed directly from any previous version to this version. To upgrade firmware, please refer to the Mellanox Firmware Tools (MFT) package at:

[http://www.mellanox.com/page/management\\_tools](http://www.mellanox.com/page/management_tools)

## 1.5 PRM Revision Compatibility

Firmware Rev 11.1500.0106 complies with the *Mellanox Switches Programmer's Reference Manual (PRM)*, Rev 1.45 or later.

## 2 Changes and New Features in Rev 11.1500.0106

*Table 5 - Firmware Rev 11.1500.0106 Changes and New Features*

| Category | Description   |
|----------|---|
| General  | Added support for IB telemetry, Top Talkers.<br>See “Congestion Telemetry” section in Mellanox Switches PRM (Programmer's Reference Manual).  |
| Modules  | Added support for 100GbE PSM4/LR4 modules (for more details see <a href="#">Section 1.3</a> , “Supported EDR Cables and Modules,” on page 4). |

### 3 Known Issues

Table 6 describes known issues in this firmware release and possible workarounds.

**Table 6 - Known Issues**

| Internal Ref. | Issue  |
|---------------|--|
| 955641        | <b>Description:</b> In VL arbitration, VL_HIGH_LIMIT isn't affecting VL Arbiter as expected  |
|               | <b>Workaround:</b> Arbitration Table should be set using only the low priority VL Arbitration Table  |
|               | <b>Keywords:</b> General   |
| -             | <b>Description:</b> Congestion control is not supported  |
|               | <b>Workaround:</b> N/A   |
|               | <b>Keywords:</b> General   |
| -             | <b>Description:</b> Port LEDs do not flash on system boot.   |
|               | <b>Workaround:</b> N/A   |
|               | <b>Keywords:</b> LEDs  |
| -             | <b>Description:</b> Link width reduction is not supported in this release.   |
|               | <b>Workaround:</b> N/A   |
|               | <b>Keywords:</b> Power Management  |
| -             | <b>Description:</b> If QDR is not enabled for the switch's InfiniBand Port Speed while connected to ConnectX-3/Pro or Connect-IB® FDR adapters or to SwitchX® /SwitchX®-2 FDR switches, links will rise at SDR or DDR (even if FDR is enabled) |
|               | <b>Workaround:</b> Enable QDR (in addition to FDR) when connecting to peer ports running at FDR  |
|               | <b>Keywords:</b> Interoperability  |
| -             | <b>Description:</b> Force FDR10 is not supported on EDR products.  |
|               | <b>Workaround:</b> To raise link with an FDR10 device, make sure all speeds, including EDR, are configured on Switch-IB.   |
|               | <b>Keywords:</b> Interoperability  |
| -             | <b>Description:</b> Adaptive routing and adaptive routing notification do not support 3D Torus topologies.   |
|               | <b>Workaround:</b> N/A   |
|               | <b>Keywords:</b> Network   |
| 697149        | <b>Description:</b> Link rises at DDR speed instead of FDR10 when using 100m QDR/FDR10 optical cables.   |
|               | <b>Workaround:</b> N/A   |
|               | <b>Keywords:</b> Link  |
| -             | <b>Description:</b> FDR link may rise with symbol errors on optic EDR cable longer than 30M.   |
|               | <b>Workaround:</b> N/A   |
|               | <b>Keywords:</b> Link  |

**Table 6 - Known Issues**

| Internal Ref. | Issue   |
|---------------|---|
| -             | <b>Description:</b> Fan LEDs may behave unexpectedly in the first 5 seconds of system boot. |
|               | <b>Workaround:</b> N/A  |
|               | <b>Keywords:</b> LEDs   |

## 4 Bug Fixes History

**Table 7 - Fixed Bugs List**

| Internal Ref. | Issue  |
|---------------|--|
| 1092005       | <b>Description:</b> Enable SDR speed regardless of cable supported speeds  |
|               | <b>Keywords:</b> Link  |
|               | <b>Discovered in Release:</b> 11.1400.0102   |
|               | <b>Fixed in Release:</b> 11.1500.0106  |
| -             | <b>Description:</b> VL arbitration does not distribute traffic as expected in case of multiple VLs.                            |
|               | <b>Keywords:</b> General   |
|               | <b>Discovered in Release:</b> 11.1200.0102   |
|               | <b>Fixed in Release:</b> 11.1300.0100  |
| -             | <b>Description:</b> In rare cases, FDR links may rise with errors. (Improved BER performance.)                                 |
|               | <b>Keywords:</b> Link  |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.1200.0102  |
| -             | <b>Description:</b> Insertion of QDR cables into a Switch-IB™ based switch overwrites non-volatile fields (rx_output_amp/emp). |
|               | <b>Keywords:</b> System Management   |
|               | <b>Discovered in Release:</b> 11.1100.0072   |
|               | <b>Fixed in Release:</b> 11.1200.0102  |
| -             | <b>Description:</b> Bubbles appear as symbol errors when link raises FDR 1x.   |
|               | <b>Keywords:</b> Link  |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.1200.0102  |
| -             | <b>Description:</b> PSU fans set to work with 60% max speed by default.  |
|               | <b>Keywords:</b> Chassis Management  |
|               | <b>Discovered in Release:</b> 11.0350.0394   |
|               | <b>Fixed in Release:</b> 11.1100.0072  |
| -             | <b>Description:</b> The command “show interfaces ib * transceiver” shows no cable is connected while link is up.               |
|               | <b>Keywords:</b> Chassis Management  |
|               | <b>Discovered in Release:</b> 11.0350.0394   |
|               | <b>Fixed in Release:</b> 11.1100.0072  |

**Table 7 - Fixed Bugs List**

| Internal Ref. | Issue  |
|---------------|--|
| 690231        | <b>Description:</b> Fixed MSGI data reading.   |
|               | <b>Keywords:</b> General   |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.0350.0394  |
| -             | <b>Description:</b> In rare cases, link may degrade speed from EDR or FDR to a lower speed. In other cases physical errors may increment.      |
|               | <b>Keywords:</b> Link  |
|               | <b>Discovered in Release:</b> 11.0350.0372   |
|               | <b>Fixed in Release:</b> 11.0350.0394  |
| -             | <b>Description:</b> Minimum fan speed may drop.  |
|               | <b>Keywords:</b> Temperature   |
|               | <b>Discovered in Release:</b> 11.0200.0120   |
|               | <b>Fixed in Release:</b> 11.0204.0124  |
| -             | <b>Description:</b> Bit error rate is not optimal on QDR links.  |
|               | <b>Keywords:</b> Link  |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.0200.0118  |
| -             | <b>Description:</b> Only connections to Switch-IB™, ConnectX®-3, ConnectX-3 Pro, Connect-IB™, and SwitchX® family devices are supported.       |
|               | <b>Keywords:</b> Interoperability  |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.0100.0112  |
| -             | <b>Description:</b> Connecting a cable longer than 30m to ConnectX-3, ConnectX-3 Pro or Connect-IB plat- forms causes interoperability issues. |
|               | <b>Keywords:</b> Interoperability  |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.0100.0112  |
| -             | <b>Description:</b> Packets are lost on private linear forwarding table (pLFT).  |
|               | <b>Keywords:</b> pLFT  |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.0100.0112  |
| -             | <b>Description:</b> Port LEDs may continue to blink even after a bad cable is removed.   |
|               | <b>Keywords:</b> Chassis Management  |
|               | <b>Discovered in Release:</b> 11.1.1002  |
|               | <b>Fixed in Release:</b> 11.0100.0112  |

## 5 Firmware Changes and New Feature History

**Table 8 - History of Major Changes and New Features**

| Category            | Description  |
|---------------------|--|
| <b>11.1430.0160</b> |  |
| General             | Added support for Adaptive Routine (AR) optimizations with ConnectX-5 (RC Mode)  |
| Link                | Added support for Force EDR on Switch IB systems As described in Mellanox Switches Programmer's Reference Manual (PRM) under PTYS Register                         |
| <b>11.1400.0102</b> |  |
| General             | Added support for IB telemetry, Congestion Monitoring-Thresholds (See Mellanox Switches PRM (Programmer's Reference Manual) - section 9.7 - Congestion Telemetry). |
| General             | Added support for Additional Port Counters Extended (See IB Specification Vol 1-Release-1.3, MgtWG 1.3 Errata).  |
| General             | Added support for IB Router Port (Port 37) Counters (See IB Specification Vol 1-Release-1.3)   |
| <b>11.1300.0126</b> |  |
| General             | Added support for burst/traffic histograms (described in Vendor Specific MAD PRM Rev 1.3, Section 3.33 – Mellanox Performance Histograms)                          |
| Link                | Added support for Port PHY Link Mode (PLLM) register (For register description, See Switch PRM - PPLM - Port Phy Link Mode)  |
| Link                | Added support for QSFP copper cables which do not publish attenuation in the memory map  |